

Information on environmental incidents
at the oil fields of "Surgutneftegas" PJSC in 2022

No.	Date of an incident	Place of an incident	Cause of an environmental incident	The area of land and water objects contamination (hectares), type of terrain	Measures taken in response to an incident	Administrative investigations to determine guilt (penalties, claims)
1	27.04.2022	The area of well-pad No. 76 of the Nizhne-Sortymyskoye field. High-pressure water pipeline.	Internal corrosion	0.025 dry land	<ol style="list-style-type: none"> 1. Spill localization. 2. Saline water pumpdown, gathering and removal of the contaminated soil. 3. Technical measures for land reclamation. 4. Biological measures for land reclamation. 	Not carried out.
2	14.05.2022	The area of BPS-5A of the Zapadno-Surgutskoye field, the Kalinovaya River	Spill source is not related to "Surgutneftegas" PJSC	water surface	<ol style="list-style-type: none"> 1. Localization by installing booms. 2. Collection of iridescent film. 	Not carried out.
3	09.06.2022	The area of well-pad No. 14 of the Kamynskoye field. Oil and gas pipeline	Internal corrosion	0.075 dry land	<ol style="list-style-type: none"> 1. Spill localization. 2. Oil pumpdown, gathering and removal of the contaminated soil. 3. Technical measures for land reclamation. 4. Biological measures for land reclamation. 	Not carried out.
4	26.10.2022	The area of drilling pad No. 217 of the Zapadno-Surgutskoye field OIL PIPELINE	Illegal (criminal) taps into the pipeline	0.0137 dry land	<ol style="list-style-type: none"> 1. Spill localization. 2. Oil pumpdown, gathering and removal of the contaminated soil. 3. Technical measures for land reclamation. 4. Biological measures for land reclamation. 	Not carried out.